

Test report No.: 22-00037-CP-PR-00
Manufacturer: OKB Sp. z o.o., Poland
Type: OB



Test report
No.: 22-00037-CP-PRG-00

Test of a type of a vehicle
with regard to ECE Regulation No. **14.00**
taking into consideration amendment No. **14.09, Supplement 1**
Approval subject: **Strength of safety belt anchorages**

Approval status	
Granting of a type approval	N/A
Extension/correction to type approval no.	N/A

Test report only.

Extract from report for demonstration purposes. Only full version can be used for approval purposes.
Wyciąg z raportu dla celów demonstracyjnych. Tylko pełna wersja może być użyta do procedury aprobaty technicznych zabudowy.
Auszug aus Prüfbericht zu Demonstrationszwecken. Nur die Vollversion kann zu Genehmigungszwecken verwendet werden.

Test report No.: 22-00037-CP-PR-00
Manufacturer: OKB Sp. z o.o., Poland
Type: OB



I. General

Type OB
Name and address of manufacturer OKB Sp. z o.o.
ul. Szkolna 9, Bukowiec
95-006 Brójce
Poland
Reference number of information folder MOBIFRAME/02/2022-00
Date of issue of information folder 24.08.2022

II. Test results

Refer to the Annex

III. Enclosures

Information Folder

IV. Statement of conformity

The mentioned information folder and the type described therein are in accordance with the test basis mentioned above. Sampling plan or method result from the requirements of the test basis. The worst-case configuration was selected in accordance with process description "Requirements for Test Reports (AS-PB-T-02)". Valid decision rule in accordance with ILAC G8:2019, 4.2.1: in question of meeting the limits the measurement uncertainty was ignored.

The manufacturer is responsible for the information (III.) and the test specimens provided by him. The test results relate only to the test specimens as received and mentioned (II.). The test specimens are representative for the type described (III.).

The test report may be reproduced and published in full and by the client only. It can be reproduced partially with the written permission of the test laboratory only.

Test report No.: 22-00037-CP-PR-00
Manufacturer: OKB Sp. z o.o., Poland
Type: OB




Auto Service

TÜV SÜD Auto Service GmbH is designated as Technical Service by:

Approval authority	Country	Registration number
Kraftfahrt-Bundesamt (KBA)	Germany	KBA-P 00100-10
Vehicle Certification Agency (VCA)	United Kingdom	VCA-TS-006
Approval Authority of the Netherlands (RDW)	The Netherlands	RDWT-082-xx
National Standards Authority of Ireland (NSAI)	Ireland	Technical Service Number: 49
Vehicle Safety Certification Center (VSCC)	Taiwan	DE04-06-2
Société Nationale de Certification et d'Homologation s.à r.l.	Luxembourg	13/B(g)
Swedish Transport Agency (STA)	Sweden	TT 0024

München, 26. 08. 2022


Ing. Vít Bursík
Authorized signatory



Extract from report for demonstration purposes. Only full version can be used for approval purposes.
Wyciąg z raportu dla celów demonstracyjnych. Tylko pełna wersja może być użyta do procedury zmian technicznych zabudowy.
Auszug aus Prüfbericht zu Demonstrationszwecken. Nur die Vollversion kann für Genehmigungszwecke verwendet werden.

Test report No.: 22-00037-CP-PR-00
 Manufacturer: OKB Sp. z o.o., Poland
 Type: OB



1.7. Table1: vehicles types:

Manufacturer	Commercial description / Type	Wheelbase
Daimler / Mercedes-Benz	Sprinter (906, 907)	3250, 3665, 4325
	Sprinter (910)	3259, 3924
VW	Crafter (2E__)	3250, 3665, 4325
	Crafter (SYN__ e.g. SYN1E, SYN2E, SYN2Z)	3640, 4490
	T5 (7H_, 7E_, 7J_)	3000, 3400
	T6, T6.1 (7H_, 7E_, 7J_)	3000, 3400
Citroen	Jumper (Y)	3000, 3450, 4035
Peugeot	Boxer (Y)	3000, 3450, 4035
Fiat	Ducato (250)	3000, 3450, 4035
	Talento (FJL, FFL)	3098, 3498
Opel/Vauxhall	Vivaro (F7)	3098, 3498
	Movano (Y)	3000, 3450, 4035
Renault	Trafic (FL, L)	3098, 3498
	Trafic 2014 (JL, L)	3098, 3498
Ford	Transit (FC_)	3300, 3750, 3954
	Transit Custom (FA_, FC_)	2933, 3300
Nissan	NV300, Primastar	3098, 3498
MAN	TGE (SYN__ e.g. SYN1E, SYN2E, SYN2Z)	3640, 4490
Freightliner/Dodge	Sprinter	3250, 3665, 4325
RAM	ProMaster	3000, 3450, 4035

Extract from report for demonstration purposes. Only full version can be used for approval.
 Wyciąg z raportu dla celów demonstracyjnych. Tylko pełna wersja może być użyta do procedury / Genehmigungsverfahren.
 Auszug aus Prüfbericht zu Demonstrationszwecken. Nur die Vollversion kann zu Genehmigungsverfahren verwendet werden.

Test report No.:
Manufacturer:
Type:

22-00037-CP-PR-00
OKB Sp. z o.o., Poland
OB

3.4.3 MOBIFRAME type OB-S and OB-V in Mercedes Sprinter 906 and 907 bodywork.

Pre-test:



Post-test



3.4.4 MOBIFRAME type OB-T driver's and passenger's seats Ford Transit bodywork.

Pre-test:



Post-test



Test report No.: 22-00036-CP-PR-00
Manufacturer: OKB SP. Z O.O., Poland
Type: OB



Auto Service

Test report
No.: 22-00036-CP-PRG-00

Test of a type of a vehicle
with regard to ECE Regulation No. **17.00**
taking into consideration amendment No. **17.09, Supplement 1**
Approval subject: **Strength of seats and their anchorages and head restraints**

Approval status	
Granting of a type approval	N/A
Extension/correction to type approval no.	N/A

Test report only.

Extract from report for demonstration purposes only full version can be used for approval purposes.
Wyciąg z raportu dla celów demonstracyjnych. Tylko pełna wersja może być użyta do procedury zmian technicznych zabudowy.
Auszug aus Prüfbericht zu Demonstrationszwecken. Nur die Vollversion kann zu Genehmigungszwecken verwendet werden.

Test report No.: 22-00036-CP-PR-00
Manufacturer: OKB SP. Z O.O., Poland
Type: OB



Auto Service

I. General

Type OB
Name and address of manufacturer OKB Sp. z o.o.
ul. Szkolna 9, Bukowiec
95-006 Brójce
Poland
Reference number of information folder MOBIFRAME/01/2022-00
Date of issue of information folder 24.08.2022

II. Test results

Refer to the Annex

III. Enclosures

Information Folder

IV. Statement of conformity

The mentioned information folder and the type described therein are in accordance with the test basis mentioned above. Sampling plan or method result from the requirements of the test basis. The worst-case configuration was selected in accordance with process description "Requirements for Test Reports (AS-PB-T-02)". Valid decision rule in accordance with ILAC G8:2019, 4.2.1: in question of meeting the limits the measurement uncertainty was ignored.

The manufacturer is responsible for the information (III.) and the test specimens provided by him. The test results relate only to the test specimens as received and mentioned (II.). The test specimens are representative for the type described (III.).

The test report may be reproduced and published in full and by the client only. It can be reproduced partially with the written permission of the test laboratory only.

Test report No.: 22-00036-CP-PR-00
Manufacturer: OKB SP. Z O.O., Poland
Type: OB



Auto Service

TÜV SÜD Auto Service GmbH is designated as Technical Service by:

Approval authority	Country	Registration number
Kraftfahrt-Bundesamt (KBA)	Germany	KBA-P 00100-10
Vehicle Certification Agency (VCA)	United Kingdom	VCA-TS-006
Approval Authority of the Netherlands (RDW)	The Netherlands	RDWT-082-xx
National Standards Authority of Ireland (NSAI)	Ireland	Technical Service Number: 49
Vehicle Safety Certification Center (VSCC)	Taiwan	DE04-06-2
Société Nationale de Certification et d'Homologation s.à r.l.	Luxembourg	13/B(g)
Swedish Transport Agency (STA)	Sweden	TT 0024

München, 26.08.2022




Ing. Vít Bursík
Authorized signatory

Extract from report for demonstration purposes. Only full version can be used for approval purposes.
Wyciąg z raportu dla celów demonstracyjnych. Tylko pełna wersja może być użyta do procedury zmian technicznych zabudowy.
Auszug aus Prüfbericht zu Demonstrationszwecken. Nur die Vollversion kann zu Genehmigungszwecken verwendet werden.

Test report No.: 22-00036-CP-PR-00
 Manufacturer: OKB SP. Z O.O., Poland
 Type: OB



Auto Service

1.7. Table1: vehicles types:

Manufacturer	Commercial description / Type	Wheelbase
Daimler / Mercedes-Benz	Sprinter (906, 907)	3250, 3665, 4325
	Sprinter (910)	3259, 3924
VW	Crafter (2E_)	3250, 3665, 4325
	Crafter (SYN__ e.g. SYN1E, SYN2E, SYN2Z)	3640, 4490
	T5 (7H_, 7E_, 7J_)	3000, 3400
	T6, T6.1 (7H_, 7E_, 7J_)	3000, 3400
Citroen	Jumper (Y)	3000, 3450, 4035
Peugeot	Boxer (Y)	3000, 3450, 4035
Fiat	Ducato (250)	3000, 3450, 4035
	Talento (FJL, FFL)	3098, 3498
Opel/Vauxhall	Vivaro (F7)	3098, 3498
	Movano (Y)	3000, 3450, 4035
Renault	Trafic (FL, L)	3098, 3498
	Trafic 2014 (JL, L)	3098, 3498
Ford	Transit (FC_)	3300, 3750, 3954
	Transit Custom (FA_, FC_)	2933, 3300
Nissan	NV300, Primastar	3098, 3498
MAN	TGE (SYN__ e.g. SYN1E, SYN2E, SYN2Z)	3640, 4490
Freightliner/Dodge	Sprinter	3250, 3665, 4325
RAM	ProMaster	3000, 3450, 4035

Extract from report for demonstration purposes. Only full version can be used for approval of technical drawings.
 Wyciąg z raportu dla celów demonstracyjnych. Tylko pełna wersja może być użyta do procedury zatwierdzenia rysunków technicznych.
 Auszug aus Prüfbericht zu Demonstrationszwecken. Nur die Vollversion kann zu Genehmigungsverfahren verwendet werden.

Test report No.: 22-00036-CP-PR-00
Manufacturer: OKB SP. Z O.O., Poland
Type: OB



Auto Service

Photo of seats from point 3.3.3 – frontal impact





Photo before test

Photo after test



Enclosure 3: SEAT ANCHORAGES



	Date: 24.08.2022
MOBIFRAME/02/2022-00	Page / pages: 10/23